

Continue



the material's resistance to crack growth in elastic-plastic materials. KIC Transition Factor): Assesses the fracture toughness in linear-elasticity by quantifying the critical stress intensity at which a crack initiates. These techniques are grounded in practical applications and provide a comprehensive understanding of material behavior under various conditions. Data obtained from these tests are crucial for designing safer, more resilient engineering structures. Parameters such as UTS, yield strength, fatigue limit, J-integral, and KIC are standardized metrics that ensure consistency and reliability in fracture analysis. Linear Elastic Fracture Mechanics (LEFM) is a critical field within materials science and engineering, focusing on the behavior of cracks in materials governed by linear elasticity. LEFM is predicated on the assumption that material deformation is elastic and the stress around a crack tip can be characterized by the Stress Intensity Factor (K). The primary objective of LEFM is to predict the onset of crack growth and its subsequent propagation under various loading conditions. This is achieved by examining three modes of crack surface displacement: Mode I (opening mode), Mode II (sliding mode), and Mode III (tearing mode). Key to LEFM is the concept of the stress intensity factor (K), which quantifies the stress state near the tip of a crack caused by a remote load or residual stresses. For a given material, fracture occurs when the applied stress intensity reaches a critical value, known as the fracture toughness (K_{IC}). This fracture toughness is a material property that signifies the ability of a material to resist the propagation of a crack. LEFM is widely utilized in engineering applications to ensure the structural integrity of components, predicting the remaining life of structures, and preventing catastrophic failures by enabling the design of materials and structures that can withstand unexpected loads and defects. Microstructure and Toughness Evaluation When evaluating the microstructure and toughness of a material, it is essential to consider several factors including grain size, phase distribution, and the presence of defects or inclusions. Grain size plays a pivotal role; finer grains typically enhance toughness due to their ability to arrest crack propagation. Phase distribution, including the presence of different metallurgical phases, influences the mechanical properties and toughness. For instance, the presence of martensite can increase strength, while phases like ferrite and pearlite can provide ductility and toughness. Additionally, the evaluation of defects, such as voids and inclusions, is critical as they can act as stress concentrators and initiation sites for cracks, thereby reducing the material's overall toughness. Advanced characterization techniques, such as scanning electron microscopy (SEM) and transmission electron microscopy (TEM), alongside mechanical testing methods like Charpy impact tests, are utilized to comprehensively assess the microstructure and toughness of materials. Understanding these characteristics enables the optimization of materials for enhanced performance in demanding applications. Reference sources Xometry; Brittle Failure - Definition, Causes, and Prevention This article provides a detailed overview of brittle failure, including its definition, the causes behind it, and strategies for prevention. It is a valuable resource for understanding the fundamental aspects of brittle fracture in metals. Read more here Inspectioneering: Brittle Fracture Inspectioneering offers an in-depth examination of brittle fracture, highlighting how this damage mechanism can cause cracking without warning. The article includes practical insights into the characteristics and ramifications of brittle fractures in various applications. Read more here Petrosync: Guide To Brittle Fracture - Prevention Acts for Engineers This guide outlines preventive measures engineers can take to mitigate the risks associated with brittle fracture. It covers essential concepts such as fracture toughness and the conditions that make materials susceptible to sudden, catastrophic failure. Read more here Frequently Asked Questions (FAQs) Q: What is brittle fracture? A: Brittle fracture is the sudden and rapid failure of a brittle material, such as ceramics, where there is little to no plastic deformation of the material before the fracture occurs. This type of fracture in metals is characterized by a swift crack propagation. Q: How does a brittle fracture occur? A: Brittle fracture occurs when a material is subjected to high stress and the atomic bonds within the material cannot support the applied stress, leading to a rapid crack initiation and propagation. The fracture often happens at low temperatures and in materials with low ductility. Q: What materials are susceptible to brittle fracture? A: Brittle materials such as ceramics and some high-strength steels are particularly susceptible to brittle fracture. These materials display little to no plastic deformation before failure. Ductile materials, on the other hand, tend to deform plastically and thus are less prone to brittle fracture. Q: How does temperature affect the risk of brittle fracture? A: Low temperatures increase the risk of brittle fracture as the ductility of materials decreases with decreasing temperature, making them more brittle and susceptible to sudden fracture under stress. Q: What role do defects play in brittle fractures? A: Defects such as cracks, voids, and inclusions act as stress concentrators within a material. At these points, the local stress can exceed the material's yield strength, leading to crack initiation and an increased risk of brittle fracture. Regular fracture assessment is crucial in identifying and mitigating such defects. Q: What is the difference between brittle fracture and ductile fracture? A: Brittle fracture occurs with minimal plastic deformation and is usually rapid, while ductile fracture involves significant plastic deformation before failure. In ductile fracture, the material often displays necking and a more gradual failure process. Q: How can welding affect the risk of brittle fracture? A: Improper welding can introduce defects and residual stresses, which increase the risk of brittle fracture. Additionally, the heat-affected zone (HAZ) of the weld can be more brittle, leading to increased susceptibility. Proper welding techniques and post-weld treatments are essential to minimize these risks. Q: How can one prevent brittle fracture? A: To prevent brittle fracture, it is important to use materials with sufficient ductility, conduct thorough fracture assessments, avoid defects and stress concentrators, and control temperature and applied stress levels. Proper material selection and regular maintenance are also crucial in minimizing risks. Q: Why is steel sometimes considered susceptible to brittle fracture? A: Certain high-strength steels can be susceptible to brittle fracture, especially at low temperatures or when they contain manufacturing defects. Proper heat treatment and avoiding corrosive environments can help reduce this susceptibility. Q: What is cleavage fracture and how does it relate to brittle fracture? A: Cleavage fracture is a type of brittle fracture where the material separates along specific crystallographic planes. This occurs in brittle materials with low ductility and high strength, resulting in a fracture surface that appears faceted and intergranular. This page provides the chapters on brittle fracture from the "DOE Fundamentals Handbook: Material Science," DOE-HDBK-1017/1-93, U.S. Department of Energy, Jan 1993. Metals that can sustain substantial plastic strain or deformation before fracturing exhibit ductile fracture. Usually a large part of the plastic flow is concentrated near the fracture faces. Metals that fracture with a relatively small or negligible amount of plastic strain exhibit brittle fracture. Cracks propagate rapidly. Brittle failure results from cleavage (splitting along definite planes). Ductile fracture is better than brittle fracture, because ductile fracture occurs over a period of time, whereas brittle fracture is fast, and can occur (with flaws) at lower stress levels than a ductile fracture. Figure 1 shows the basic types of fracture. Brittle cleavage fracture is of the most concern in this module. Brittle cleavage fracture occurs in materials with a high strain-hardening rate and relatively low cleavage strength or great sensitivity to multi-axial stress. Figure 1: Basic Fracture Types Many metals that are ductile under some conditions become brittle if the conditions are altered. The effect of temperature on the nature of the fracture is of considerable importance. Many steels exhibit ductile fracture at elevated temperatures and brittle fracture at low temperatures. The temperature above which a material is ductile and below which it is brittle is known as the Nil-Ductility Transition (NDT) temperature. This temperature is not precise, but varies according to prior mechanical and heat treatment and the nature and amounts of impurity elements. It is determined by some form of drop-weight test (for example, the Izod or Charpy tests). Ductility is an essential requirement for steels used in the construction of reactor vessels; therefore, the NDT temperature is of significance in the operation of these vessels. Small grain size tends to increase ductility and results in a decrease in NDT temperature. Grain size is controlled by heat treatment in the specifications and manufacturing of reactor vessels. The NDT temperature can also be lowered by small additions of selected alloying elements such as nickel and manganese to low-carbon steels. Of particular importance is the shifting of the NDT temperature to the right (Figure 2), when the reactor vessel is exposed to fast neutrons. The reactor vessel is continuously exposed to fast neutrons that escape from the core. Consequently, during operation the reactor vessel is subjected to an increasing fluence (flux) of fast neutrons, and as a result the NDT temperature increases steadily. It is not likely that the NDT temperature will approach the normal operating temperature of the steel. However, there is a possibility that when the reactor is being shut down or during an abnormal cooldown, the temperature may fall below the NDT value while the internal pressure is still high. The reactor vessel is susceptible to brittle fracture at this point. Therefore, special attention must be given to the effect of neutron irradiation on the NDT temperature of the steels used in fabricating reactor pressure vessels. The Nuclear Regulatory Commission requires that a reactor vessel material surveillance program be conducted in water-cooled power reactors in accordance with ASTM Standards (designation E 185-73). Pressure vessels are also subject to cyclic stress. Cyclic stress arises from pressure and/or temperature cycles on the metal. Cyclic stress can lead to fatigue failure. Fatigue failure, discussed in more detail in Module 5, can be initiated by microscopic cracks and notches and even by grinding and machining marks on the surface. The same (or similar) defects also favor brittle fracture. Stress-Temperature Curves One of the biggest concerns with brittle fracture is that it can occur at stresses well below the yield strength (stress corresponding to the transition from elastic to plastic behavior) of the material, provided certain conditions are present. These conditions are: a flaw such as a crack; a stress of sufficient intensity to develop a small deformation at the crack tip; and a temperature low enough to promote brittle fracture. The relationship between these conditions is best described using a generalized stress-temperature diagram for crack initiation and arrest as shown in Figure 2. Figure 2: Stress-Temperature Diagram for Crack Initiation and Arrest Figure 2 illustrates that as the temperature goes down, the tensile strength (Curve A) and the yield strength (Curve B) increase. The increase in tensile strength, sometimes known as the ultimate strength (a maximum of increasing strain on the stress-strain curve), is less than the increase in the yield point. At some low temperature, on the order of 10°F for carbon steel, the yield strength and tensile strength coincide. At this temperature and below, there is no yielding when a failure occurs. Hence, the failure is brittle. The temperature at which the yield and tensile strength coincide is the NDT temperature. When a small flaw is present, the tensile strength follows the dashed Curve C. At elevated temperatures, Curves A and C are identical. At lower temperatures, approximately 50°F above the NDT temperature for material with no flaws, the tensile strength curve drops to the yield curve and then follows the yield curve to lower temperatures. At the point where Curves C and B meet, there is a new NDT temperature. Therefore, if a flaw exists, any failure at a temperature equal or below the NDT temperature for flawed material will be brittle. Crack Initiation and Propagation As discussed earlier in this chapter, brittle failure generally occurs because a flaw or crack propagates throughout the material. The start of a fracture at low stresses is determined by the cracking tendencies at the tip of the crack. If a plastic flow exists at the tip, the structure is not endangered because the metal mass surrounding the crack will support the stress. When brittle fracture occurs (under the conditions for brittle fracture stated above), the crack will initiate and propagate through the material at great speeds (speed of sound). It should be noted that smaller grain size, higher temperature, and lower stress tend to mitigate crack initiation. Larger grain size, lower temperatures, and higher stress tend to favor crack propagation. There is a stress level below which a crack will not propagate at any temperature. This is called the lower fracture propagation stress. As the temperature increases, a higher stress is required for a crack to propagate. The relationship between the temperature and the stress required for a crack to propagate is called the crack arrest curve, which is shown on Figure 2 as Curve D. At temperatures above that indicated on this curve, crack propagation will not occur. Fracture Toughness Fracture toughness is an indication of the amount of stress required to propagate a preexisting flaw. The fracture toughness of a metal depends on the following factors. Metal composition Metal temperature Extent of deformations to the crystal structure Metal grain size Metal crystalline form The intersection of the crack arrest curve with the yield curve (Curve B) is called the fracture transition elastic (FTE) point. The temperature corresponding to this point is normally about 60°F above the NDT temperature. This temperature is also known as the Reference Temperature - Nil-ductility Transition (RTNDT) and is determined in accordance with ASME Section III (1974 edition), NB 2300. The FTE is the temperature above which plastic deformation accompanies all fractures or the highest temperature at which fracture propagation can occur under purely elastic loads. The intersection of the crack arrest curve (Curve D) and the tensile strength or ultimate strength, curve (Curve A) is called the fracture transition plastic (FTP) point. The temperature corresponding with this point is normally about 120°F above the NDT temperature. Above this temperature, only ductile fractures occur. Figure 3 is a graph of stress versus temperature, showing fracture initiation curves for various flaw sizes. Figure 3: Fracture Diagram It is clear from the above discussion that we must operate above the NDT temperature to be certain that no brittle fracture can occur. For greater safety, it is desirable that operation be limited above the FTE temperature, or NDT + 60°F. Under such conditions, no brittle fracture can occur for purely elastic loads. As previously discussed, irradiation of the pressure vessel can raise the NDT temperature over the lifetime of the reactor pressure vessel, restricting the operating temperatures and stress on the vessel. It should be clear that this increase in NDT can lead to significant operating restrictions, especially after 25 years to 30 years of operation where the NDT can raise 200°F to 300°F. Thus, if the FTE was 60°F at the beginning of vessel life and a change in the NDT of 300°F occurred over a period of time, the reactor coolant would have to be raised to more than 360°F before full system pressure could be applied. PDH Classroom offers a continuing education course based on this brittle fracture reference page. This course can be used to fulfill PDH credit requirements for maintaining your PE license. Now that you've read this reference page, earn credit for it! Failure can be defined, in general, as an event that does not accomplish its intended purpose. Failure of a material component is the loss of ability to function normally. Components of a system can fail one of many ways, for example excessive deformation, fracture, corrosion, burning out, degradation of specific properties (thermal, electrical, or magnetic), etc. Main types of Failures in materials are : brittle failure , ductile failure , fatigue and creep fracture or failure.Reasons Of Material Failure - Structural elements and machine elements can fail to perform their intended functions in three general ways: excessive elastic deformation, excessive plastic deformation or yielding, and fracture. Under the category of failure due to excessive elastic deformation, for example: too flexible machine shaft can cause rapid wear of bearing. On the other hand sudden buckling type of failure may occur. Failures due to excessive elastic deformation are controlled by the modulus of elasticity, not by the strength of the material. The most effective way to increase stiffness of a component is by tailoring the shape or dimensions. Yielding or plastic deformation may render a component useless after a certain limit. This failure is controlled by the yield strength of the material. At room temperature, continued loading over the yielding point may lead to strain hardening followed by fracture. However at elevated temperatures, failure occurs in form of time-dependent yielding known as creep. Fracture involves complete disruption of continuity of a component. It starts with initiation of a crack, followed by crack propagation. Fracture of materials may occur in three ways - brittle Failure/ductile Failure, fatigue or progressive fracture, delayed fracture. Ductile/brittle Failure occurs over short period of time, and distinguishable.Fracture Fracture is a form of failure, and is defined as the separation or fragmentation of a solid body into two or more parts under the action of stress. Fracture that occurs over a very short time period and under simple loading conditions (static i.e. constant or slowly changing) is considered here. Fracture under complex condition, for example alternating stress, is considered in later sections.Brittle Failure /Fracture: Brittle Failure / fracture that takes place with little or no preceding plastic deformation. It occurs often at unpredictable levels of stress, by rapid crack propagation. The direction of crack propagation is very nearly perpendicular to the direction of applied tensile stress. This crack propagation corresponds to successive and repeated breaking to atomic bonds along specific crystallographic planes, and hence called cleavage fracture. This fracture is also said to be transgranular because crack propagates through grains. Thus it has a grainy or faceted texture. Most brittle fractures occur in a transgranular manner. However, brittle fracture can occur in intergranular manner i.e. crack propagates along grain boundaries. This happens only if grain boundaries contain a brittle film or if the grain-boundary region has been embrittled by the segregation of detrimental elements.Brittle failure exam brittle fracture in metals is believed to take place in three stages - (1) plastic deformation that causes dislocation pile-ups at obstacles,(2) micro-crack nucleation as a result of build-up of shear stresses,(3) eventual crack propagation under applied stress aided by stored elastic energy.As mentioned earlier, brittle fracture occurs without any warning sign, thus it needs to be avoided. Hence brittle fracture and its mechanism have been analyzed to a great extent compared to ductile fracture. Brittle fracture usually occurs at stress levels well below those predicted theoretically from the inherent strength due to atomic or molecular bonds. This situation in some respects is analogous to the discrepancy between the theoretical strength shear strength of perfect crystals and their observed lower yield strength values. link to Top Branches of Mechanical Engineering link to Shree Ram Ayodhya Murti, idol - Vector . Wallart The term ductile and brittle is used to distinguish failures of materials characteristics by high and low toughness respectively. Brittle Fracture is the sudden & very fast cracking of material or equipment under stress. A brittle fracture occurs without any plastic deformation (No thinning or necking) or little deformation only by direct separation along crystallographic planes due to a simple breaking of atomic bonds. In brittle fracture, materials show no warning before failure, hence brittle fracture can be catastrophic in nature. After failure material broke into many pieces with little to no deformation in shape. The surface appearance of brittle fracture is relatively smooth and is often shiny in appearance. Although not all brittle fracture is perfectly smooth some brittle fracture demonstrates Chevron markings appear in the fracture area. In a Charpy Impact test, brittle metal will absorb a small amount of energy when impact tested, while a tough ductile metal absorbs a large amount of energy. Pure brittle fracture is called cleavage fracture, corrosion, burning out, degradation of specific properties (thermal, electrical, or magnetic), etc. Main types of Failures in materials are : brittle failure , ductile failure , fatigue and creep fracture or failure.Reasons Of Material Failure - Structural elements and machine elements can fail to perform their intended functions in three general ways: excessive elastic deformation, excessive plastic deformation or yielding, and fracture. Under the category of failure due to excessive elastic deformation, for example: too flexible machine shaft can cause rapid wear of bearing. On the other hand sudden buckling type of failure may occur. Failures due to excessive elastic deformation are controlled by the modulus of elasticity, not by the strength of the material. The most effective way to increase stiffness of a component is by tailoring the shape or dimensions. Yielding or plastic deformation may render a component useless after a certain limit. This failure is controlled by the yield strength of the material. At room temperature, continued loading over the yielding point may lead to strain hardening followed by fracture. However at elevated temperatures, failure occurs in form of time-dependent yielding known as creep. Fracture involves complete disruption of continuity of a component. It starts with initiation of a crack, followed by crack propagation. Fracture of materials may occur in three ways - brittle Failure/ductile Failure, fatigue or progressive fracture, delayed fracture. Ductile/brittle Failure occurs over short period of time, and distinguishable.Fracture Fracture is a form of failure, and is defined as the separation or fragmentation of a solid body into two or more parts under the action of stress. Fracture that occurs over a very short time period and under simple loading conditions (static i.e. constant or slowly changing) is considered here. Fracture under complex condition, for example alternating stress, is considered in later sections.Brittle Failure /Fracture: Brittle Failure / fracture that takes place with little or no preceding plastic deformation. It occurs often at unpredictable levels of stress, by rapid crack propagation. The direction of crack propagation is very nearly perpendicular to the direction of applied tensile stress. This crack propagation corresponds to successive and repeated breaking to atomic bonds along specific crystallographic planes, and hence called cleavage fracture. This fracture is also said to be transgranular because crack propagates through grains. Thus it has a grainy or faceted texture. Most brittle fractures occur in a transgranular manner. However, brittle fracture can occur in intergranular manner i.e. crack propagates along grain boundaries. This happens only if grain boundaries contain a brittle film or if the grain-boundary region has been embrittled by the segregation of detrimental elements.Brittle failure exam brittle fracture in metals is believed to take place in three stages - (1) plastic deformation that causes dislocation pile-ups at obstacles,(2) micro-crack nucleation as a result of build-up of shear stresses,(3) eventual crack propagation under applied stress aided by stored elastic energy.As mentioned earlier, brittle fracture occurs without any warning sign, thus it needs to be avoided. Hence brittle fracture and its mechanism have been analyzed to a great extent compared to ductile fracture. Brittle fracture usually occurs at stress levels well below those predicted theoretically from the inherent strength due to atomic or molecular bonds. This situation in some respects is analogous to the discrepancy between the theoretical strength shear strength of perfect crystals and their observed lower yield strength values. link to Top Branches of Mechanical Engineering link to Shree Ram Ayodhya Murti, idol - Vector . Wallart The term ductile and brittle is used to distinguish failures of materials characteristics by high and low toughness respectively. Brittle Fracture is the sudden & very fast cracking of material or equipment under stress. A brittle fracture occurs without any plastic deformation (No thinning or necking) or little deformation only by direct separation along crystallographic planes due to a simple breaking of atomic bonds. In brittle fracture, materials show no warning before failure, hence brittle fracture can be catastrophic in nature. After failure material broke into many pieces with little to no deformation in shape. The surface appearance of brittle fracture is relatively smooth and is often shiny in appearance. Although not all brittle fracture is perfectly smooth some brittle fracture demonstrates Chevron markings appear in the fracture area. In a Charpy Impact test, brittle metal will absorb a small amount of energy when impact tested, while a tough ductile metal absorbs a large amount of energy. Pure brittle fracture is called cleavage fracture, corrosion, burning out, degradation of specific properties (thermal, electrical, or magnetic), etc. Main types of Failures in materials are : brittle failure , ductile failure , fatigue and creep fracture or failure.Reasons Of Material Failure - Structural elements and machine elements can fail to perform their intended functions in three general ways: excessive elastic deformation, excessive plastic deformation or yielding, and fracture. Under the category of failure due to excessive elastic deformation, for example: too flexible machine shaft can cause rapid wear of bearing. On the other hand sudden buckling type of failure may occur. Failures due to excessive elastic deformation are controlled by the modulus of elasticity, not by the strength of the material. The most effective way to increase stiffness of a component is by tailoring the shape or dimensions. Yielding or plastic deformation may render a component useless after a certain limit. This failure is controlled by the yield strength of the material. At room temperature, continued loading over the yielding point may lead to strain hardening followed by fracture. However at elevated temperatures, failure occurs in form of time-dependent yielding known as creep. Fracture involves complete disruption of continuity of a component. It starts with initiation of a crack, followed by crack propagation. Fracture of materials may occur in three ways - brittle Failure/ductile Failure, fatigue or progressive fracture, delayed fracture. Ductile/brittle Failure occurs over short period of time, and distinguishable.Fracture Fracture is a form of failure, and is defined as the separation or fragmentation of a solid body into two or more parts under the action of stress. Fracture that occurs over a very short time period and under simple loading conditions (static i.e. constant or slowly changing) is considered here. Fracture under complex condition, for example alternating stress, is considered in later sections.Brittle Failure /Fracture: Brittle Failure / fracture that takes place with little or no preceding plastic deformation. It occurs often at unpredictable levels of stress, by rapid crack propagation. The direction of crack propagation is very nearly perpendicular to the direction of applied tensile stress. This crack propagation corresponds to successive and repeated breaking to atomic bonds along specific crystallographic planes, and hence called cleavage fracture. This fracture is also said to be transgranular because crack propagates through grains. Thus it has a grainy or faceted texture. Most brittle fractures occur in a transgranular manner. However, brittle fracture can occur in intergranular manner i.e. crack propagates along grain boundaries. This happens only if grain boundaries contain a brittle film or if the grain-boundary region has been embrittled by the segregation of detrimental elements.Brittle failure exam brittle fracture in metals is believed to take place in three stages - (1) plastic deformation that causes dislocation pile-ups at obstacles,(2) micro-crack nucleation as a result of build-up of shear stresses,(3) eventual crack propagation under applied stress aided by stored elastic energy.As mentioned earlier, brittle fracture occurs without any warning sign, thus it needs to be avoided. Hence brittle fracture and its mechanism have been analyzed to a great extent compared to ductile fracture. Brittle fracture usually occurs at stress levels well below those predicted theoretically from the inherent strength due to atomic or molecular bonds. This situation in some respects is analogous to the discrepancy between the theoretical strength shear strength of perfect crystals and their observed lower yield strength values. link to Top Branches of Mechanical Engineering link to Shree Ram Ayodhya Murti, idol - Vector . Wallart The term ductile and brittle is used to distinguish failures of materials characteristics by high and low toughness respectively. Brittle Fracture is the sudden & very fast cracking of material or equipment under stress. A brittle fracture occurs without any plastic deformation (No thinning or necking) or little deformation only by direct separation along crystallographic planes due to a simple breaking of atomic bonds. In brittle fracture, materials show no warning before failure, hence brittle fracture can be catastrophic in nature. After failure material broke into many pieces with little to no deformation in shape. The surface appearance of brittle fracture is relatively smooth and is often shiny in appearance. Although not all brittle fracture is perfectly smooth some brittle fracture demonstrates Chevron markings appear in the fracture area. In a Charpy Impact test, brittle metal will absorb a small amount of energy when impact tested, while a tough ductile metal absorbs a large amount of energy. Pure brittle fracture is called cleavage fracture, corrosion, burning out, degradation of specific properties (thermal, electrical, or magnetic), etc. Main types of Failures in materials are : brittle failure , ductile failure , fatigue and creep fracture or failure.Reasons Of Material Failure - Structural elements and machine elements can fail to perform their intended functions in three general ways: excessive elastic deformation, excessive plastic deformation or yielding, and fracture. Under the category of failure due to excessive elastic deformation, for example: too flexible machine shaft can cause rapid wear of bearing. On the other hand sudden buckling type of failure may occur. Failures due to excessive elastic deformation are controlled by the modulus of elasticity, not by the strength of the material. The most effective way to increase stiffness of a component is by tailoring the shape or dimensions. Yielding or plastic deformation may render a component useless after a certain limit. This failure is controlled by the yield strength of the material. At room temperature, continued loading over the yielding point may lead to strain hardening followed by fracture. However at elevated temperatures, failure occurs in form of time-dependent yielding known as creep. Fracture involves complete disruption of continuity of a component. It starts with initiation of a crack, followed by crack propagation. Fracture of materials may occur in three ways - brittle Failure/ductile Failure, fatigue or progressive fracture, delayed fracture. Ductile/brittle Failure occurs over short period of time, and distinguishable.Fracture Fracture is a form of failure, and is defined as the separation or fragmentation of a solid body into two or more parts under the action of stress. Fracture that occurs over a very short time period and under simple loading conditions (static i.e. constant or slowly changing) is considered here. Fracture under complex condition, for example alternating stress, is considered in later sections.Brittle Failure /Fracture: Brittle Failure / fracture that takes place with little or no preceding plastic deformation. It occurs often at unpredictable levels of stress, by rapid crack propagation. The direction of crack propagation is very nearly perpendicular to the direction of applied tensile stress. This crack propagation corresponds to successive and repeated breaking to atomic bonds along specific crystallographic planes, and hence called cleavage fracture. This fracture is also said to be transgranular because crack propagates through grains. Thus it has a grainy or faceted texture. Most brittle fractures occur in a transgranular manner. However, brittle fracture can occur in intergranular manner i.e. crack propagates along grain boundaries. This happens only if grain boundaries contain a brittle film or if the grain-boundary region has been embrittled by the segregation of detrimental elements.Brittle failure exam brittle fracture in metals is believed to take place in three stages - (1) plastic deformation that causes dislocation pile-ups at obstacles,(2) micro-crack nucleation as a result of build-up of shear stresses,(3) eventual crack propagation under applied stress aided by stored elastic energy.As mentioned earlier, brittle fracture occurs without any warning sign, thus it needs to be avoided. Hence brittle fracture and its mechanism have been analyzed to a great extent compared to ductile fracture. Brittle fracture usually occurs at stress levels well below those predicted theoretically from the inherent strength due to atomic or molecular bonds. This situation in some respects is analogous to the discrepancy between the theoretical strength shear strength of perfect crystals and their observed lower yield strength values. link to Top Branches of Mechanical Engineering link to Shree Ram Ayodhya Murti, idol - Vector . Wallart The term ductile and brittle is used to distinguish failures of materials characteristics by high and low toughness respectively. Brittle Fracture is the sudden & very fast cracking of material or equipment under stress. A brittle fracture occurs without any plastic deformation (No thinning or necking) or little deformation only by direct separation along crystallographic planes due to a simple breaking of atomic bonds. In brittle fracture, materials show no warning before failure, hence brittle fracture can be catastrophic in nature. After failure material broke into many pieces with little to no deformation in shape. The surface appearance of brittle fracture is relatively smooth and is often shiny in appearance. Although not all brittle fracture is perfectly smooth some brittle fracture demonstrates Chevron markings appear in the fracture area. In a Charpy Impact test, brittle metal will absorb a small amount of energy when impact tested, while a tough ductile metal absorbs a large amount of energy. Pure brittle fracture is called cleavage fracture, corrosion, burning out, degradation of specific properties (thermal, electrical, or magnetic), etc. Main types of Failures in materials are : brittle failure , ductile failure , fatigue and creep fracture or failure.Reasons Of Material Failure - Structural elements and machine elements can fail to perform their intended functions in three general ways: excessive elastic deformation, excessive plastic deformation or yielding, and fracture. Under the category of failure due to excessive elastic deformation, for example: too flexible machine shaft can cause rapid wear of bearing. On the other hand sudden buckling type of failure may occur. Failures due to excessive elastic deformation are controlled by the modulus of elasticity, not by the strength of the material. The most effective way to increase stiffness of a component is by tailoring the shape or dimensions. Yielding or plastic deformation may render a component useless after a certain limit. This failure is controlled by the yield strength of the material. At room temperature, continued loading over the yielding point may lead to strain hardening followed by fracture. However at elevated temperatures, failure occurs in form of time-dependent yielding known as creep. Fracture involves complete disruption of continuity of a component. It starts with initiation of a crack, followed by crack propagation. Fracture of materials may occur in three ways - brittle Failure/ductile Failure, fatigue or progressive fracture, delayed fracture. Ductile/brittle Failure occurs over short period of time, and distinguishable.Fracture Fracture is a form of failure, and is defined as the separation or fragmentation of a solid body into two or more parts under the action of stress. Fracture that occurs over a very short time period and under simple loading conditions (static i.e. constant or slowly changing) is considered here. Fracture under complex condition, for example alternating stress, is considered in later sections.Brittle Failure /Fracture: Brittle Failure / fracture that takes place with little or no preceding plastic deformation. It occurs often at unpredictable levels of stress, by rapid crack propagation. The direction of crack propagation is very nearly perpendicular to the direction of applied tensile stress. This crack propagation corresponds to successive and repeated breaking to atomic bonds along specific crystallographic planes, and hence called cleavage fracture. This fracture is also said to be transgranular because crack propagates through grains. Thus it has a grainy or faceted texture. Most brittle fractures occur in a transgranular manner. However, brittle fracture can occur in intergranular manner i.e. crack propagates along grain boundaries. This happens only if grain boundaries contain a brittle film or if the grain-boundary region has been embrittled by the segregation of detrimental elements.Brittle failure exam brittle fracture in metals is believed to take place in three stages - (1) plastic deformation that causes dislocation pile-ups at obstacles,(2) micro-crack nucleation as a result of build-up of shear stresses,(3) eventual crack propagation under applied stress aided by stored elastic energy.As mentioned earlier, brittle fracture occurs without any warning sign, thus it needs to be avoided. Hence brittle fracture and its mechanism have been analyzed to a great extent compared to ductile fracture. Brittle fracture usually occurs at stress levels well below those predicted theoretically from the inherent strength due to atomic or molecular bonds. This situation in some respects is analogous to the discrepancy between the theoretical strength shear strength of perfect crystals and their observed lower yield strength values. link to Top Branches of Mechanical Engineering link to Shree Ram Ayodhya Murti, idol - Vector . Wallart The term ductile and brittle is used to distinguish failures of materials characteristics by high and low toughness respectively. Brittle Fracture is the sudden & very fast cracking of material or equipment under stress. A brittle fracture occurs without any plastic deformation (No thinning or necking) or little deformation only by direct separation along crystallographic planes due to a simple breaking of atomic bonds. In brittle fracture, materials show no warning before failure, hence brittle fracture can be catastrophic in nature. After failure material broke into many pieces with little to no deformation in shape. The surface appearance of brittle fracture is relatively smooth and is often shiny in appearance. Although not all brittle fracture is perfectly smooth some brittle fracture demonstrates Chevron markings appear in the fracture area. In a Charpy Impact test, brittle metal will absorb a small amount of energy when impact tested, while a tough ductile metal absorbs a large amount of energy. Pure brittle fracture is called cleavage fracture, corrosion, burning out, degradation of specific properties (thermal, electrical, or magnetic), etc. Main types of Failures in materials are : brittle failure , ductile failure , fatigue and creep fracture or failure.Reasons Of Material Failure - Structural elements and machine elements can fail to perform their intended functions in three general ways: excessive elastic deformation, excessive plastic deformation or yielding, and fracture. Under the category of failure due to excessive elastic deformation, for example: too flexible machine shaft can cause rapid wear of bearing. On the other hand sudden buckling type of failure may occur. Failures due to excessive elastic deformation are controlled by the modulus of elasticity, not by the strength of the material. The most effective way to increase stiffness of a component is by tailoring the shape or dimensions. Yielding or plastic deformation may render a component useless after a certain limit. This failure is controlled by the yield strength of the material. At room temperature, continued loading over the yielding point may lead to strain hardening followed by fracture. However at elevated temperatures, failure occurs in form of time-dependent yielding known as creep. Fracture involves complete disruption of continuity of a component. It starts with initiation of a crack, followed by crack propagation. Fracture of materials may occur in three ways - brittle Failure/ductile Failure, fatigue or progressive fracture, delayed fracture. Ductile/brittle Failure occurs over short period of time, and distinguishable.Fracture Fracture is a form of failure, and is defined as the separation or fragmentation of a solid body into two or more parts under the action of stress. Fracture that occurs over a very short time period and under simple loading conditions (static i.e. constant or slowly changing) is considered here. Fracture under complex condition, for example alternating stress, is considered in later sections.Brittle Failure /Fracture: Brittle Failure / fracture that takes place with little or no preceding plastic deformation. It occurs often at unpredictable levels of stress, by rapid crack propagation. The direction of crack propagation is very nearly perpendicular to the direction of applied tensile stress. This crack propagation corresponds to successive and repeated breaking to atomic bonds along specific crystallographic planes, and hence called cleavage fracture. This fracture is also said to be transgranular because crack propagates through grains. Thus it has a grainy or faceted texture. Most brittle fractures occur in a transgranular manner. However, brittle fracture can occur in intergranular manner i.e. crack propagates along grain boundaries. This happens only if grain boundaries contain a brittle film or if the grain-boundary region has been embrittled by the segregation of detrimental elements.Brittle failure exam brittle fracture in metals is believed to take place in three stages - (1) plastic deformation that causes dislocation pile-ups at obstacles,(2) micro-crack nucleation as a result of build-up of shear stresses,(3) eventual crack propagation under applied stress aided by stored elastic energy.As mentioned earlier, brittle fracture occurs without any warning sign, thus it needs to be avoided. Hence brittle fracture and its mechanism have been analyzed to a great extent compared to ductile fracture. Brittle fracture usually occurs at stress levels well below those predicted theoretically from the inherent strength due to atomic or molecular bonds. This situation in some respects is analogous to the discrepancy between the theoretical strength shear strength of perfect crystals and their observed lower yield strength values. link to Top Branches of Mechanical Engineering link to Shree Ram Ayodhya Murti, idol - Vector . Wallart The term ductile and brittle is used to distinguish failures of materials characteristics by high and low toughness respectively. Brittle Fracture is the sudden & very fast cracking of material or equipment under stress. A brittle fracture occurs without any plastic deformation (No thinning or necking) or little deformation only by direct separation along crystallographic planes due to a simple breaking of atomic bonds. In brittle fracture, materials show no warning before failure, hence brittle fracture can be catastrophic in nature. After failure material broke into many pieces with little to no deformation in shape. The surface appearance of brittle fracture is relatively smooth and is often shiny in appearance. Although not all brittle fracture is perfectly smooth some brittle fracture demonstrates Chevron markings appear in the fracture area. In a Charpy Impact test, brittle metal will absorb a small amount of energy when impact tested, while a tough ductile metal absorbs a large amount of energy. Pure brittle fracture is called cleavage fracture, corrosion, burning out, degradation of specific properties (thermal, electrical, or magnetic), etc. Main types of Failures in materials are : brittle failure , ductile failure , fatigue and creep fracture or failure.Reasons Of Material Failure - Structural elements and machine elements can fail to perform their intended functions in three general ways: excessive elastic deformation, excessive plastic deformation or yielding, and fracture. Under the category of failure due to excessive elastic deformation, for example: too flexible machine shaft can cause rapid wear of bearing. On the other hand sudden buckling type of failure may occur. Failures due to excessive elastic deformation are controlled by the modulus of elasticity, not by the strength of the material. The most effective way to increase stiffness of a component is by tailoring the shape or dimensions. Yielding or plastic deformation may render a component useless after a certain limit. This failure is controlled by the yield strength of the material. At room temperature, continued loading over the yielding point may lead to strain hardening followed by fracture. However at elevated temperatures, failure occurs in form of time-dependent yielding known as creep. Fracture involves complete disruption of continuity of a component. It starts with initiation of a crack, followed by crack propagation. Fracture of materials may occur in three ways - brittle Failure/ductile Failure, fatigue or progressive fracture, delayed fracture. Ductile/brittle Failure occurs over short period of time, and distinguishable.Fracture Fracture is a form of failure, and is defined as the separation or fragmentation of a solid body into two or more parts under the action of stress. Fracture that occurs over a very short time period and under simple loading conditions (static i.e. constant or slowly changing) is considered here. Fracture under complex condition, for example alternating stress, is considered in later sections.Brittle Failure /Fracture: Brittle Failure / fracture that takes place with little or no preceding plastic deformation. It occurs often at unpredictable levels of stress, by rapid crack propagation. The direction of crack propagation is very nearly perpendicular to the direction of applied tensile stress. This crack propagation corresponds to successive and repeated breaking to atomic bonds along specific crystallographic planes, and hence called cleavage fracture. This fracture is also said to be transgranular because crack propagates through grains. Thus it has a grainy or faceted texture. Most brittle fractures occur in a transgranular manner. However, brittle fracture can occur in intergranular manner i.e. crack propagates along grain boundaries. This happens only if grain boundaries contain a brittle film or if the grain-boundary region has been embrittled by the segregation of detrimental elements.Brittle failure exam brittle fracture in metals is believed to take place in three stages - (1) plastic deformation that causes dislocation pile-ups at obstacles,(2) micro-crack nucleation as a result of build-up of shear stresses,(3) eventual crack propagation under applied stress aided by stored elastic energy.As mentioned earlier, brittle fracture occurs without any warning sign, thus it needs to be avoided. Hence brittle fracture and its mechanism have been analyzed to a great extent compared to ductile fracture. Brittle fracture usually occurs at stress levels well below those predicted theoretically from the inherent strength due to atomic or molecular bonds. This situation in some respects is analogous to the discrepancy between the theoretical strength shear strength of perfect crystals and their observed lower yield strength values. link to Top Branches of Mechanical Engineering link to Shree Ram Ayodhya Murti, idol - Vector . Wallart The term ductile and brittle is used to distinguish failures of materials characteristics by high and low toughness respectively. Brittle Fracture is the sudden & very fast cracking of material or equipment under stress. A brittle fracture occurs without any plastic deformation (No thinning or necking) or little deformation only by direct separation along crystallographic planes due to a simple breaking of atomic bonds. In brittle fracture, materials show no warning before failure, hence brittle fracture can be catastrophic in nature. After failure material broke into many pieces with little to no deformation in shape. The surface appearance of brittle fracture is relatively smooth and is often shiny in appearance. Although not all brittle fracture is perfectly smooth some brittle fracture demonstrates Chevron markings appear in the fracture area. In a Charpy Impact test, brittle metal will absorb a small amount of energy when impact tested, while a tough ductile metal absorbs a large amount of energy. Pure brittle fracture is called cleavage fracture, corrosion, burning out, degradation of specific properties (thermal, electrical, or magnetic), etc. Main types of Failures in materials are : brittle failure , ductile failure , fatigue and creep fracture or failure.Reasons Of Material Failure - Structural elements and machine elements can fail to perform their intended functions in three general ways: excessive elastic deformation, excessive plastic deformation or yielding, and fracture. Under the category of failure due to excessive elastic deformation, for example: too flexible machine shaft can cause rapid wear of bearing. On the other hand sudden buckling type of failure may occur. Failures due to excessive elastic deformation are controlled by the modulus of elasticity, not by the strength of the material. The most effective way to increase stiffness of a component is by tailoring the shape or dimensions. Yielding or plastic deformation may render a component useless after a certain limit. This failure is controlled by the yield strength of the material. At room temperature, continued loading over the yielding point may lead to strain hardening followed by fracture. However at elevated temperatures, failure occurs in form of time-dependent yielding known as creep. Fracture involves complete disruption of continuity of a component. It starts with initiation of a crack, followed by crack propagation. Fracture of materials may occur in three ways - brittle Failure/ductile Failure, fatigue or progressive fracture, delayed fracture. Ductile/brittle Failure occurs over short period of time, and distinguishable.Fracture Fracture is a form of failure, and is defined as the separation or fragmentation of a solid body into two or more parts under the action of stress. Fracture that occurs over a very short time period and under simple loading conditions (static i.e. constant or slowly changing) is considered here. Fracture under complex condition, for example alternating stress, is considered in later sections.Brittle Failure /Fracture: Brittle Failure / fracture that takes place with little or no preceding plastic deformation. It occurs often at unpredictable levels of stress, by rapid crack propagation. The direction of crack propagation is very nearly perpendicular to the direction of applied tensile stress. This crack propagation corresponds to successive and repeated breaking to atomic bonds along specific crystallographic planes, and hence called cleavage fracture. This fracture is also said to be transgranular because crack propagates through grains. Thus it has a grainy or faceted texture. Most brittle fractures occur in a transgranular manner. However, brittle fracture can occur in intergranular manner i.e. crack propagates along grain boundaries. This happens only if grain boundaries contain a brittle film or if the grain-boundary region has been embrittled by the segregation of detrimental elements.Brittle failure exam brittle fracture in metals is believed to take place in three stages - (1) plastic deformation that causes dislocation pile-ups at obstacles,(2) micro-crack nucleation as a result of build-up of shear stresses,(3) eventual crack propagation under applied stress aided by stored elastic energy.As mentioned earlier, brittle fracture occurs without any warning sign, thus it needs to be avoided. Hence brittle fracture and its mechanism have been analyzed to a great extent compared to ductile fracture. Brittle fracture usually occurs at stress levels well below those predicted theoretically from the inherent strength due to atomic or molecular bonds. This situation in some respects is analogous to the discrepancy between the theoretical strength shear strength of perfect crystals and their observed lower yield strength values. link to Top Branches of Mechanical Engineering link to Shree Ram Ayodhya Murti, idol - Vector . Wallart The term ductile and brittle is used to distinguish failures of materials characteristics by high and low toughness respectively. Brittle Fracture is the sudden & very fast cracking of material or equipment under stress. A brittle fracture occurs without any plastic deformation (No thinning or necking) or little deformation only by direct separation along crystallographic planes due to a simple breaking of atomic bonds. In brittle fracture, materials show no warning before failure, hence brittle fracture can be catastrophic in nature. After failure material broke into many pieces with little to no deformation in shape. The surface appearance of brittle fracture is relatively smooth and is often shiny in appearance. Although not all brittle fracture is perfectly smooth some brittle fracture demonstrates Chevron markings appear in the fracture area. In a Charpy Impact test, brittle metal will absorb a small amount of energy when impact tested, while a tough ductile metal absorbs a large amount of energy. Pure brittle fracture is called cleavage fracture, corrosion, burning out, degradation of specific properties (thermal, electrical, or magnetic), etc. Main types of Failures in materials are : brittle failure , ductile failure , fatigue and creep fracture or failure.Reasons Of Material Failure - Structural elements and machine elements can fail to perform their intended functions in three general ways: excessive elastic deformation, excessive plastic deformation or yielding, and fracture. Under the category of failure due to excessive elastic deformation, for example: too flexible machine shaft can cause rapid wear of bearing. On the other hand sudden buckling type of failure may occur. Failures due to excessive elastic deformation are controlled by the modulus of elasticity, not by the strength of the material. The most effective way to increase stiffness of a component is by tailoring the shape or dimensions. Yielding or plastic deformation may render a component useless after a certain limit. This failure is controlled by the yield strength of the material. At room temperature, continued loading over the yielding point may lead to strain hardening followed by fracture. However at elevated temperatures, failure occurs in form of time-dependent yielding known as creep. Fracture involves complete disruption of continuity of a component. It starts with initiation of a crack, followed by crack propagation. Fracture of materials may occur in three ways - brittle Failure/ductile Failure, fatigue or progressive fracture, delayed fracture. Ductile/brittle Failure occurs over short period of time, and distinguishable.Fracture Fracture is a form of failure, and is defined as the separation or fragmentation of a solid body into two or more parts under the action of stress. Fracture that occurs over a very short time period and under simple loading conditions (static i.e. constant or slowly changing) is considered here. Fracture under complex condition, for example alternating stress, is considered in later sections.Brittle Failure /Fracture: Brittle Failure / fracture that takes place with little or no preceding plastic deformation. It occurs often at unpredictable levels of stress, by rapid crack propagation. The direction of crack propagation is very nearly perpendicular to the direction of applied tensile stress. This crack propagation corresponds to successive and repeated breaking to atomic bonds along specific crystallographic planes, and hence called cleavage fracture. This fracture is also said to be transgranular because crack propagates through grains. Thus it has a grainy or faceted texture. Most brittle fractures occur in a transgranular manner. However, brittle fracture can occur in intergranular manner i.e. crack propagates along grain boundaries. This happens only if grain boundaries contain a brittle film or if the grain-boundary region has been embrittled by the segregation of detrimental elements.Brittle failure exam brittle fracture in metals is believed to take place in three stages - (1) plastic deformation that causes dislocation pile-ups at obstacles,(2) micro-crack nucleation as a result of build-up of shear stresses,(3) eventual crack propagation under applied stress aided by stored elastic energy.As mentioned earlier, brittle fracture occurs without any warning sign, thus it needs to be avoided. Hence brittle fracture and its mechanism have been analyzed to a great extent compared to ductile fracture. Brittle fracture usually occurs at stress levels well below those predicted theoretically from the inherent strength due to atomic or molecular bonds. This situation in some respects is analogous to the discrepancy between the theoretical strength shear strength of perfect crystals and their observed lower yield strength values. link to Top Branches of Mechanical Engineering link to Shree Ram Ayodhya Murti, idol - Vector . Wallart The term ductile and brittle is used to distinguish failures of materials characteristics by high and low toughness respectively. Brittle Fracture is the sudden & very fast cracking of material or equipment under stress. A brittle fracture occurs without any plastic deformation (No thinning or necking) or little deformation only by direct separation along crystallographic planes due to a simple breaking of atomic bonds. In brittle fracture, materials show no warning before failure, hence brittle fracture can be catastrophic in nature. After failure material broke into many pieces with little to no deformation in shape. The surface appearance of brittle fracture is relatively smooth and is often shiny in appearance. Although not all brittle fracture is perfectly smooth some brittle fracture demonstrates Chevron markings appear in the fracture area. In a Charpy Impact test, brittle metal will absorb a small amount of energy when impact tested, while a tough ductile metal absorbs a large amount of energy. Pure brittle fracture is called cleavage fracture, corrosion, burning out, degradation of specific properties (thermal, electrical, or magnetic), etc. Main types of Failures in materials are : brittle failure , ductile failure , fatigue and creep fracture or failure.Reasons Of Material Failure - Structural elements and machine elements can fail to perform their intended functions in three general ways: excessive elastic deformation, excessive plastic deformation or yielding, and fracture. Under the category of failure due to excessive elastic deformation, for example: too flexible machine shaft can cause rapid wear of bearing. On the other hand sudden buckling type of failure may occur. Failures due to excessive elastic deformation are controlled by the modulus of elasticity, not by the strength of the material. The most effective way to increase stiffness of a component is by tailoring the shape or dimensions. Yielding or plastic deformation may render a component useless after a certain limit. This failure is controlled by the yield strength of the material. At room temperature, continued loading over the yielding point may lead to strain hardening followed by fracture. However at elevated temperatures, failure occurs in form of time-dependent yielding known as creep. Fracture involves complete disruption of continuity of a component. It starts with initiation of a crack, followed by crack propagation. Fracture of materials may occur in three ways - brittle Failure/ductile Failure, fatigue or progressive fracture, delayed fracture. Ductile/brittle Failure occurs over short period of time, and distinguishable.Fracture Fracture is a form of failure, and is defined as the separation or fragmentation of a solid body into two or more parts under the action of stress. Fracture that occurs over a very short time period and under simple loading conditions (static i.e. constant or slowly changing) is considered here. Fracture under complex condition, for example alternating stress, is considered in later sections.Brittle Failure /Fracture: Brittle Failure / fracture that takes place with little or no preceding plastic deformation. It occurs often at unpredictable levels of stress, by rapid crack propagation. The direction of crack propagation is very nearly perpendicular to the direction of applied tensile stress. This crack propagation corresponds to successive and repeated breaking to atomic bonds along specific crystallographic planes, and hence called cleavage fracture. This fracture is also said to be transgranular because crack propagates through grains. Thus it has a grainy or faceted texture. Most brittle fractures occur in a transgranular manner. However, brittle fracture can occur in intergranular manner i.e. crack propagates along grain boundaries. This happens only if grain boundaries contain a brittle film or if the grain-boundary region has been embrittled by the segregation of detrimental elements.Brittle failure exam brittle fracture in metals is believed to take place in three stages - (1) plastic deformation that causes dislocation pile-ups at obstacles,(2) micro-crack nucleation as a result of build-up of shear stresses,(3) eventual crack propagation under applied stress aided by stored elastic energy.As mentioned earlier, brittle fracture occurs without any warning sign, thus it needs to be avoided. Hence brittle fracture and its mechanism have been analyzed to a great extent compared to ductile fracture. Brittle fracture usually occurs at stress levels well below those predicted theoretically from the inherent strength due to atomic or molecular bonds. This situation in some respects is analogous to the discrepancy between the theoretical strength shear strength of perfect crystals and their observed lower yield strength values. link to Top Branches of Mechanical Engineering link to Shree Ram Ayodhya Murti, idol - Vector . Wallart The term ductile and brittle is used to distinguish failures of materials characteristics by high and low toughness respectively. Brittle Fracture is the sudden & very fast cracking of material or equipment under stress. A brittle fracture occurs without any plastic deformation (No thinning or necking) or little deformation only by direct separation along crystallographic planes due to a simple breaking of atomic bonds. In brittle fracture, materials show no warning before failure, hence brittle fracture can be catastrophic in nature. After failure material broke into many pieces with little to no deformation in shape. The surface appearance of brittle fracture is relatively smooth and is often shiny in appearance. Although not all brittle fracture is perfectly smooth some brittle fracture demonstrates Chevron markings appear in the fracture area. In a Charpy Impact test, brittle metal will absorb a small amount of energy when impact tested, while a tough