

Continue

























The default option in Windows is to display the battery icon at bottom-left corner of the screen in the taskbar. If the battery icon is missing, you wont be able to see how much battery life is left on your LaptopThe most common reason for Battery Icon missing or disappearing from Taskbar is due to Battery Icon being moved to System Tray or due to Battery display in the Taskbar being accidentally disabled.Apart from this the problem of missing battery icon on a Windows computer can also be caused due to the drivers becoming outdated or corrupted. Battery Icon Missing in Windows 11/10If the Battery icon is missing from the taskbar on your computer, you should be able to fix the problem using troubleshooting methods as provided below in this guide.1. Check Overflow Pane (System Tray)/Start by checking the Overflow Pane (System Tray) to rule out the possibility of the battery icon being moved out to the Overflow Pane. This can happen, if the Taskbar is crowded with multiple icons.1. Click on the Up Arrow Icon located in the Taskbar and see if the Battery Icon is available.2. If the Battery Icon is available, you can place it on the Taskbar by dragging the Battery Icon from System Tray to the Taskbar.2. Enable Battery Icon Display in the Taskbars mentioned above, the problem might be due to the battery icon display in the Taskbar being accidentally disabled or switched OFF during a Windows update.1. Right-click on the Taskbar and click on Taskbar settings.2. Scroll down in the right-pane and click on Taskbar Corner Overflow tab > On the next screen, move the toggle next to Power to ON position>Note: Taskbar Corner Overflow Tab is not available in all versions of Windows 11.After this, the battery icon should be available on the Taskbar or in the System Tray. If it becomes available in System Tray, you can drag it to the Taskbar.3. Restart Windows ExplorerSome users have reported fixing the move of missing battery icon by closing Windows Explorer service and restarting it back again.1. Right-click on the Start button and click on Task Manager.2. On the Task Manager screen, make sure you are on the Processes Tab > right-click on Windows Explorer and click on the Restart option.Hopefully, one of these methods should help you restore the missing battery icon on your laptop.4. Scan For Hardware ChangesSometimes, the case of Missing Battery Icon in Windows is due to Operating System detecting a change in Hardware or Hardware Settings on your computer.1. Right-click on the Start button and click on Device Manager.2. On Device Manager screen, click on the Action tab in top-menu bar and select Scan for Hardware changes option.3. Now, check the Notification Area in the Taskbar and see if the Battery Icon is now visible.5. Enable/Disable Battery DriversFollow the steps below to disable the Driver for Battery on your laptop and Enable the Driver back again.1. Right-click on the Start button and click on Device Manager.2. On Device Manager screen, expand Batteries section, right-click on Microsoft ACPI-Compliant Control Method Battery and click on Disable Device option.3. Next, right-click on Microsoft ACPI-Compliant Control Method Battery and click on Enable Device option.4. Restart your computer and see if the battery icon is now visible in the Notification Area of the Taskbar.6. Power Icon Greyed OutIf the power icon is greyed out, you can follow the steps below to Enable the power icon.1. Right-click on the Start button and click on Device Manager.2. On Device Manager screen, expand Batteries section, right-click on Microsoft ACPI-Compliant Control Method Battery and click on Disable Device option.3. Next, right-click on Microsoft ACPI-Compliant Control Method Battery and click on Enable Device option.4. Restart the computer and see if the battery icon is now visible in the notification area of the Taskbar.The battery icon on your Windows 10 PC should appear in the system tray area of your Taskbar, close to the time and date. It helps you keep track of your device's battery level and can be helpful when you use your PC in areas with no power. However, you might find that the battery icon is missing from your system traymaking it hard for you to keep track of your PCs battery status. In this article, well show you how to bring back the battery icon if its missing in your system tray. 1. Check if the Battery Icon is Disabled or Not If you cant see the battery icon on your system tray, the first step is to check whether its missing or not. The battery icon might be available on your computer but hiding with some of your hidden items in the system tray. To check if the battery icon is hidden, tap on theupward pointing arrow on the system tray. If you find the battery icon, you can drag it and drop it back to the system tray on your taskbar. If the battery icon isnt appearing in your hidden items on the system tray, then its disabled. To fix it, apply the other methods in this article. If your battery icon isnt hidden in your system tray, its probably set to not show on the taskbar, or its disabled. If the taskbar is missing its icons and the system tray doesnt show any items, then youll first need to fix your taskbar. In case your taskbar is okay, and its only the battery icon thats missing, you can fix this issue using taskbar settings. To get started, right-click the blank area in the taskbar and select Taskbar settings in the pop-up menu. Navigate to the Notification area in the Taskbar Settings window and click Select which icons appear on the taskbar. From here, navigate to Power and check whether its button is turned on or off. You should switch the button On so that the battery icon can appear on the taskbar. In case this doesnt resolve your issue, you can try the other methods. If your battery icon is still missing after turning on the Power button in your Taskbar Settings, you should consider checking the Power settings with the troubleshooter. To do this, navigate to Windows Start Menu > PC settings > Update & Security > Troubleshoot. Scroll down and select the Power option. Click the Run the troubleshooter button. The troubleshooter will run and indicate that its resolving issues. When it finishes, check if it has resolved your issue. If the problem persists, try the other methods in this article. If your PCs battery drivers dont function normally, the battery icon will not show on the taskbar. To resolve this issue, you should restart or reinstall the battery drivers. To restart your battery drivers, press Windows Key + X and select Device Manager in the pop-up menu. On the Device Manager, double-click the Batteries option to expand it. Youll see two options: the Microsoft AC Adapter and the Microsoft ACPI-Compliant Control Method Battery. For the two options that appear, right-click on each adapter and select Disable device. After that, right-click again on each adapter and select Enable device. Restart your PC and check if the battery icon appears in your system tray. If re-enabling the battery driver doesnt work, try reinstalling the battery drivers. To do this, right-click each adapter and select Uninstall device. When you finish uninstalling the drivers, click on the Scan for hardware changes icon in the Device Manager menu. Restart your PC, and the system will reinstall the battery adapters. Your missing battery icon should now appear in the system tray. If it still doesnt appear, try the other methods that follow. You can bring back your missing Windows 10 battery icon by restarting Windows Explorer. This is fairly an easy process; heres how you can do it: Right-click in the blank area of your Taskbar and go to Task Manager. In the Processes Tab of the Taskbar, scroll down and find the Windows Explorer process. Right-click on Windows Explorer and click the Restart option. Restart your computer, and the issue should be resolved. Otherwise, you can try the other methods in this article. You can also use the Local Group Policy Editor to retrieve your missing battery icon. This feature is only available in Windows 10 Pro, Education, and Enterprise editions. However, there are steps you can follow to open the Local Group Policy Editor in your Windows 10Home edition. To restore the battery icon using the Local Group Policy, follow these steps: Press Windows Key + R, then type gpedit.msc and click Enter to open the Local Group Policy Editor. In the navigation pane on the left-hand side, go to User Configuration > Administrative Templates. In the right-hand side pane, double-click on Start Menu and Taskbar. Again, in the right-hand side pane, double-click Remove the battery meter option. A window will pop up. Select Disabled or Not Configured in the options on the pop-up window. From here, click Apply and then click OK. Restart your PC, and the battery icon should be back on your system tray. If youve tried all the solutions we mentioned so far and the issue persists, try running the System File Checker (SFC). The SFC scanner is a built-in troubleshooting tool designed to solve various system-related issues. To run an SFC scan on your Windows 10 PC, follow these steps: Press the Windows Key + R. From here, type "CMD" and click Ctrl + Shift + Enter. When you're on the User Account Control prompt, click the Yes button to run the Command Prompt as administrator. In the Command Prompt, type in the following: sfc/scannow Press Enter to continue. SFC will begin scanning your PC for corrupted or faulty files. Wait for the process to finish, and then restart your PC. Your battery icon should now show in your system tray. Were confident that one of the methods in this article should resolve your problem. But in case your battery icon still doesnt appear after applying any of the methods we provided, updating your Windows 10 PC could also help out. Weve provided several methods you can apply to bring back the battery icon if it doesnt appear in the Windows 10 system tray. Any of our suggested methods should help you resolve this issue with ease. If you cant see a battery icon on Windows 10's taskbar, it may be hidden or disabled. The icon should appear in Windows' system tray area, next to the time and date. If the battery icon is missing in Windows 10, try these methods to restore it.Instructions in this article apply to Windows 10. If you cant see a battery icon, the first thing to check is whether it is simply hidden. Select the up arrow to the left of the system tray to reveal the hidden system tray icons. If you can see the battery icon here, continue with the following steps. Otherwise, try the next method. Right-click any unselected area on the taskbar to bring up the menu. Select Taskbar settings.Alternatively, select the Windows icon, then select Settings > Personalization > Taskbar. In the Taskbar settings, scroll down to the Notification area and choose Select which icons appear on the taskbar. Scroll down the list until you find the battery icon, which is called "Power." Select its toggle switch to set it to On. You should now see the battery icon in the taskbar. If, when you select the up arrow, the battery icon isn't in the group of hidden icons, it means you'll need to enable the battery icon. Go into the Taskbar settings using one of the methods described above. Scroll down to the Notification area and select Turn system icons on or off. Scroll down and select the Power toggle switch to turn it on. The battery icon should now appear. If it doesnt, it might now just be hidden and you'll have to use the previous method to reveal it.In the vast majority of cases, the above steps will work. If the battery icon is still missing, check and install any available Windows updates, restart your computer, then try the above steps again. If the above steps dont work, you can try to disable and re-enable battery hardware in the Windows Device Manager.Ensure you are connected to external power before you start this process. Press Windows key+X to bring up the Quick Access Menu, then select Device Manager. In the Device Manager, select the Batteries category to expand it. There should be two items: Microsoft AC AdapterMicrosoft ACPI-Compliant Control Method Battery. Right-click Microsoft AC Adapter and select Disable device. A warning will appear asking you if youre sure you want to disable the device. Select Yes. Repeat steps 3 and 4 to disable the Microsoft ACPI-Compliant Control Method Battery. To re-enable the devices right-click each and select Enable device. Restart your computer and the battery icon should appear.If the battery icon doesnt appear, try the previous steps outlined above to check if the battery icon is hidden. Then, if needed, enable the battery icon.Thanks for letting us know!Get the Latest Tech News Delivered Every DaySubscribe!Tell us why! Home / How To / How to Fix the Battery Icon Missing or Greyed Out in Windows 10 Rick Akira If your computer battery icon is missing from Windows 10 taskbar or the power button system icon settings is grayed out, this article is for you. Click here to learn more. Laptop users have the advantage of taking their computer anywhere. However, this doesnt last forever, depending on the battery of your device. Most people can tell the state of their battery from a quick glance, however, some Windows 10 laptop users noticed that the battery icon is missing.The battery icon should appear in Windows 10s system tray, also called the notification area, next to the time and date. If you cant see it or its greyed out, it may have been hidden, disabled, or corrupted.In this article, were listed some useful methods you can use to try and restore it.Jump to Solution:How to fix the battery icon missing#1. Select the battery icon to appear on the taskbarIts possible that the battery icon was simply disabled or never turned on in the first place. You canfix this issueby toggling the Power option to show up in your system tray.Right-click on an empty space in your taskbar, then selectTaskbar settings. This is going to open up to the appropriate Settings app page.Scroll down until you see the Notification area section. Here, click on the Turn system icons on or off link.Locate thePower toggle, and make sure that its turned to the On setting. This will ensure that the battery icon is visible in your system tray.If you still dont see the battery icon, go back to theTaskbar settingsand click on the Select which icons appear on the taskbar link from the Notification area section.Scroll down until you seePower, then toggle the switch to its On setting. You should be able to see the battery icon in your taskbar now.#2. Disable and re-enable battery hardwareSometimes all you need to do in order to fix something is restart its device. The same goes for your laptop batteries.If the battery icon seems to be missing, try restarting the device. This signals your computer that the batteries are indeed there, making the icon re-appear.Note: Make sure to connect to an external power source before attempting this method!Press theWindows + Xkeys on your keyboard, then chooseDevice Managerfrom the Quick Access Menu.When the Device Manager loads up, locate theBatteriescategory, and expand it by clicking on the arrow icon. You should be able to see two items:Microsoft AC AdapterMicrosoft ACPI-Compliant Control Method Battery.Right-click onMicrosoft AC Adapter, then select Disable deviceoption.You should see a warning notification prompting you to confirm that you want to disable the device. Click on Yes.RepeatStep 3 andStep 4with theMicrosoft ACPI-Compliant Control Method Batterydevice.Next, re-enable both devices by right-clicking on them and choosing theEnable deviceoption.Restart your computer. You should be able to see the battery icon re-appear in your taskbar after the next boot.#3. Update Windows 10Some users report that simply switching to the newest version ofWindows 10made the battery icon re-appear.Open theSettingsapplication using the Start menu or theWindows + Ikeyboard shortcut.Click onUpdate & Security.In the Windows Update tab, click on theCheck for updatesbutton.If a new update is found, click on theInstallbutton.After your system successfully installs the newest Windows 10 update, you might be able to see the battery icon showing up and functioning again.How to fix the battery icon greyed out#1. Scan for hardware changesSimply making your laptop recognize hardware changes can re-enable the battery icon in your system tray.Press theWindows + Xkeys on your keyboard, then chooseDevice Managerfrom the Quick Access Menu.When the Device Manager loads, click on theActionmenu from the ribbon.ChooseScan for hardware changes.Expand theBatteriescategory and make sure you see both of the following two devices listed:Microsoft AC AdapterMicrosoft ACPI-Compliant Control Method Battery.Restart your computer. When it boots up, check if the battery icon shows up without being greyed out.2. Run the System File CheckerTheSystem File Checkeris a tool available in Windows 10 by default. Its also called an SFC scan, and its your quickest way to automaticallyfix corrupted system filesand other issues.Heres how to run it.Press theWindows + Rkeys on your keyboard to launch the Run utility. Type in cmd and pressCtrl + Shift + Enter. This is going to open the Command Prompt with administrative permissions. If prompted, make sure toallow the Command Prompt to make changeson your device. This means that you might need an administrator account.Type in the following command and press Enter:sfc /scannowPress Enter.Wait for the scanning process to complete.6. Check for Virus or MalwareVirus or malware can also cause issues with the battery icon on your Windows 10 machine. Therefore, its essential to scan your device for viruses and malware regularly. You can use the built-in Windows Defender or any other reputable antivirus software to scan your device.7. Create a New User Account:If all the above steps fail to restore the missing battery icon, you can create a new user account. Follow these steps to create a new user account:Press Windows + I to open the Settings app.Click on the Accounts option.Select Family & other users.Under Other users, click on the Add someone else to this PC option.Follow the on-screen instructions to create a new user account.ConclusionThe battery icon on the taskbar is an important component that helps you keep track of your devices battery life. If it goes missing, you might feel worried about the battery's status. However, the above-discussed methods can help you restore the missing battery icon on your Windows 10 machine. If you still cant restore the battery icon, you can seek assistance from a professional. Is your battery icon missing on Windows 10? Don't worry! MiniTool offers you 3 solutions to solve this problem. Keep reading and take one solution according your condition.For some reason, when I go to settings, Turn system icons on or off and then try to turn power on so that I can see how much battery power I have left, it wont let me change the settingCan anyone help me? answers.microsoft.comMany users reported that they had encounter battery icon missing Windows 10 problem. This makes them worried because they are afraid that the computer will run out of power without warning and theyll lose all of their work.Then, how to solve Windows 10 battery icon missing problem? Please keep reading to get the answer.When you find battery icon missing from taskbar windows 10, the first thing you should do is to check whether it is simply hidden. To do that, please select the up arrow to the left of the system tray to reveal the hidden system tray icons.Then, you will get a result: either you can find the battery icon in the hidden system tray or you cant.If you get the first result, you should take Fix 1. If you get the second result, you should try Fix 2 or 3.Step 1: Open Taskbar settings. You can do that through the following two ways.Right-click anywhere on the taskbar to bring up a shortcut menu and then select Taskbar settings.Click Windows icon at the lower left corner, and then go to Settings> Personalization > Taskbar.Step 2: In the Taskbar settings, you should find the Notification area and then choose Select which icons appear on the taskbar.Step 3: Scroll down to find the battery icon named Power from the list. Then, switch its toggle to On. If the power toggle is switched to Off, the battery icon will not appear on the taskbar.Fix 2. Enable the Battery IconIf you dont see battery icon when you select the up arrow, it is very possible that the battery icon is disabled. To add it back, you should enable it through the following steps:Step 1: Open the Taskbar settings and find the Notification area again. Then, select Turn system icons on or off.Step 2: Similarly, scroll down to find Power and then switch its toggle to On.In the vast majority of cases, the battery icon missing windows 10 is caused either by hiding icon or by disabling icon. In these cases, the above two methods will work and make battery icon appear again.Fix 3. Disable and Re-enable Battery HardwareIf the above methods dont work, you should try this one. This method has helped many users solve Windows 10 battery icon missing problem. As for how to do that, please refer to the following steps:Warning: Ensure your computer is connected to external power before you start this process.Step 1: Press Windows + X keys simultaneously and then choose Device Manager from the shortcut menu.Step 2: Expand Batteries category and you will find two items here: Microsoft AC Adapter; and Microsoft ACPI-Compliant Control Method Battery.Step 3: Right-click them and choose Disable Device one by one.Tip: When disabling them, a window may pop up warning that disabling this device will cause it to stop functioning. Just click Yes button to continue.Step 4: After disabling all the battery devices, you should re-enable them again. To do that, you just need to right-click each of them and select Enable device.Step 5: Restart your computer and the battery icon should appear. Windows 10 normally displays a battery icon in the notification area, also known as the system tray, when you're using a laptop or tablet. This icon shows the current battery percentage. Here's how to get it back if it vanishes. Your battery icon might still be in the notification area, but "hidden." To look for it, click the up arrow to the left of your notification icons on the taskbar. If you see the battery icon here (an area Microsoft calls the "notification area overflow pane"), simply drag and drop it back to the notification area on your taskbar. If you don't see the battery icon in the panel of hidden icons, right-click your taskbar and select "Taskbar Settings." You can also head to Settings > Personalization > Taskbar instead. Scroll down in the Settings window that appears and click "Turn system icons on or off" under Notification area. Locate the "Power" icon in the list here and toggle it to "On" by clicking it. It will reappear on your taskbar. You can also toggle other system icons on or off from here, including Clock, Volume, Network, Input Indicator, Location, Action Center, Touch Keyboard, Windows Ink Workspace, and Touchpad. If the Power option here is grayed out, Windows 10 thinks you're using a desktop PC without a battery. The taskbar's power icon won't appear on PCs without a battery. Even after you've restored the battery icon, it won't show an estimate of the remaining battery time when you mouse over it. Microsoft has disabled that feature—likely because it's generally inaccurate. You can still re-enable the battery life estimate with a registry hack.

**Windows 10 battery calibration. Battery indicator missing windows 10. Battery icon missing windows 7. Battery icon disappeared windows 10. Battery icon missing windows 10.**